

Figure 1




Figure 2




Figure 3




Figure 4




Figure 5




Figure 6




Figure 7




Figure 8




Figure 9




Figure 10

	Resolution		_	e m
			mm Motion	No. Steps to Move
Setting	Step Angle	Steps/Rev	Per Step	0.5 Micron
•	0.72	500	0.01	0.050
2	0.36	1000	0.005	0.100
3	0.288	1250	0.004	0.125
4	0.18	2000	0.0025	0.200
5	i 0.144	2500	0.002	0.250
6	0.09	4000	0.00125	0.400
7	0.072	5000	0.001	0.500
8	0.036	10000	0.0005	1.000
9	0.0288	12500	0.0004	1.250
10	0.018	20000	0.00025	2.000
11	0.0144	25000	0.0002	2.500
12	0.009	40000	0.000125	4.000
13	0.0072	50000	0.0001	5.000
14	0.00576	62500	0.00008	6.250
15	0.0036	100000	0.00005	10.000
16	0.00288	125000	0.00004	12.500

Fig. 11






Fig. 12



TWO SECTION, DUAL DIAMETER, MULTIPLE PORT PUMP

Fig. 13

TaperLock Connections



BEST AVAILABLE COPY